

42-045-00070 b1



Monroe Energy, LLC
Trainer Refinery
4101 Post Road
Trainer, PA 19061
(610) 364-8000

February 8, 2013

Mr. James Rebarchak
Regional Manager – Air Quality
Commonwealth of Pennsylvania
Pennsylvania Department of Environmental Protection
2 East Main Street
Norristown, PA 19401

RECEIVED
FEB 14 2013
3:20

RE: Monroe Energy – Trainer Refinery
Storage Tanks – 30-day Advanced Refill Notification

Dear Mr. Rebarchak:

There are two storage tanks at the Trainer Refinery that are scheduled to be out of service and refilled during 1Q 2013. In accordance with 40 CFR 63.646 – Storage Vessel Provisions of MACT CC, a 30-day advanced notification of refill is required for the tanks listed in the table below. The tanks, identification numbers, and type are listed below along with the applicable regulation.

PADEP Source ID	Refinery Tank ID	Tank Type	Applicable Regulation
137	152	IFRT	MACT CC – 40 CFR 63.120(a)(5), as referenced by 40 CFR 63.646
150	168	IFRT	MACT CC – 40 CFR 63.120(a)(5), as referenced by 40 CFR 63.646

The referenced tanks will each be refilled as soon as the scheduled work has been completed. Should you have any questions or comments regarding this notification, please contact me at (610) 364-8090.

Sincerely,

A handwritten signature in black ink that reads "Liddie S. Clark".

Liddie S. Clark, REM
Environmental Leader

cc: U.S. EPA, Region III
Director, Air Protection Division
Mail Code 3AP00
1650 Arch Street
Philadelphia, PA 19103-2029



6 A
Monroe Energy, LLC

4101 Post Road

Trainer, PA 19061

August 13, 2012

RECEIVED
AUG 21 2012
3AP20

Mr. James Rebarchak
Regional Manager - Air Quality
Commonwealth of Pennsylvania
Pennsylvania Department of Environmental Protection
2 East Main St.
Norristown, PA 19401

**RE: Monroe Energy -- Trainer Refinery Storage
Various Storage Tanks -- 30-day Advanced Refill Notifications**

Dear Mr. Rebarchak:

Various storage tanks at the Trainer Refinery are out of service and are scheduled to be refilled. In accordance with 40 CFR 63.646 – Storage Vessel Provisions of MACT CC, and in accordance with 40 CFR 60 – NSPS Kb, a 30-day advanced notification of refill is required for each tank listed in the table below. Each tank, along with the applicable regulation is shown below that this advanced notification of refill applies to.

PADEP Tank ID	Refinery Tank ID	Tank Type	Applicable Regulation
141	156	EFRT	MACT CC – 40 CFR 63.120(b)(10)(ii) as referenced by 40 CFR 63.646
134	132	IFRT	MACT CC – 40 CFR 63.120(a)(5) as referenced by 40 CFR 63.646
190	134	IFRT	NSPS Kb – 40 CFR 60.113b(a)(5)
139	154A	IFRT	NSPS Kb – 40 CFR 60.113b(a)(5)
136	151	EFRT	MACT CC – 40 CFR 63.120(b)(10)(ii) as referenced by 40 CFR 63.646
143	159	EFRT	MACT CC – 40 CFR 63.120(b)(10)(ii) as referenced by 40 CFR 63.646
152	170	EFRT	NSPS Kb – 40 CFR 60.113b(a)(5)
144	161	EFRT	MACT CC – 40 CFR 63.120(b)(10)(ii) as referenced by 40 CFR 63.646
150	168	IFRT	MACT CC – 40 CFR 63.120(a)(5) as referenced by 40 CFR 63.646
153	171	IFRT	MACT CC – 40 CFR 63.120(a)(5) as referenced by 40 CFR 63.646

Should you have any questions or comments regarding this notification, please contact me at (610) 364-8090.

Sincerely,

Liddie S. Clark

Liddie Clark
Environmental Engineer

cc: U.S. EPA, Region III
Director, Air Protection Division
Mail Code 3AP00
1650 Arch Street
Philadelphia, Pa 19103-2029

42-045-00070



Monroe Energy, LLC
4101 Post Road
Trainer, PA 19061

August 9, 2012

Mr. James Rebarchak
Regional Manager - Air Quality
Commonwealth of Pennsylvania
Pennsylvania Depart of Environmental Protection
2 East Main St.
Norristown, PA 19401

RECEIVED
AUG 14 2012
3AP20

**RE: Monroe Energy -- Trainer Refinery Storage
Storage Tanks 93 and 94 (PA DEP IDs 165 and 166) -- NSPS Kb 30-day Advanced Refill Notifications**

Dear Mr. Rebarchak:

Currently, storage tanks 93 and 94 at the Trainer Refinery are out of service for API 653 inspections. As both tanks are subject to NSPS Kb -- Standards of Performance for Volatile Organic Liquid Storage Vessels for Which Construction Reconstruction, or Modification Commenced After July 23, 1984, a 30-day advanced notification of refill is required by 40 CFR 60.113b(6)(ii).

Should you have any questions or comments regarding this notification, please contact me at (610) 755-8342.

Sincerely,

Liddie S. Clark, REM
Environmental Engineer

cc: U.S. EPA, Region III
Director, Air Protection Division
Mail Code 3AP00
1650 Arch Street
Philadelphia, Pa 19103-2029



Phillips 66 Company
Trainer Refinery
4101 Post Rd
Trainer, PA 19061

May 11, 2012

CERTIFIED MAIL – 7009 2820 0002 5401 0442

Mr. Andrew Seligman
Environmental Scientist/Enforcement Officer
Air Enforcement Division
3AP12
U.S. Environmental Protection Agency, Region III
1650 Arch Street
Philadelphia, PA 19103-2029

RECEIVED
MAY 22 2012
3AP20

Subject: Storage Tank Seal Gap Measurement Notification

Dear Mr. Seligman:

Phillips 66 Company, Trainer Refinery, in accordance with the requirements of 40 CFR §60.113b(b)(5) and 40 CFR §63.654(h)(2)(ii) notified the U.S. Environmental Protection Agency of expected Storage Tank Seal Gap Measurements in a letter dated May 10, 2012. Some tanks were inadvertently omitted from that notification. This notification replaces the May 10, 2012 notification. The following roof seal inspections and/or gap measurements are expected to be completed on the following external and internal floating roof storage tanks:

Tank 168A	Tank 116A	Tank 169A	Tank 154B	Tank 134A	Tank 156A
Tank 93	Tank 132	Tank 103A	Tank 172	Tank 151A	Tank 161A
Tank 94	Tank 159A	Tank 66A	Tank 175A	Tank 95	Tank 181
Tank 113A	Tank 164A	Tank 67A	Tank 170A	Tank 96	Tank 174A
Tank 68A	Tank 184	Tank 182	Tank 171	Tank 163A	Tank 165A
Tank 114A	Tank 185A	Tank 186A	Tank 152A	Tank 162A	Tank 166A
Tank 178					

Seal inspections for these storage tanks are scheduled to begin the week of June 1, 2012.

If you have any questions or need additional information about this notification, please contact me at (610) 364-8120.


Sincerely,

Colin J. Franks
HS&E Manager

Copy To: Mr. Kevin McLemore
Air Quality Program
Pennsylvania Department of Environmental Protection
Southeast Regional Office
2 East Main Street
Norristown, PA 19428



Phillips 66 Company
Trainer Refinery
4101 Post Rd
Trainer, PA 19061



May 10, 2012

CERTIFIED MAIL – 7009 2820 0002 5400 4656

Mr. Andrew Seligman
Environmental Scientist/Enforcement Officer
Air Enforcement Division
3AP12
U.S. Environmental Protection Agency, Region III
1650 Arch Street
Philadelphia, PA 19103-2029

RECEIVED
MAY 22 2012
3AP20

Subject: Storage Tank Seal Gap Measurement Notification

Dear Mr. Seligman:

Phillips 66 Company, Trainer Refinery, in accordance with the requirements of 40 CFR §60.113b(b)(5) and 40 CFR §63.654(h)(2)(ii) notifies the U.S. Environmental Protection Agency with this letter that roof seal inspections and/or gap measurements will be completed on the following external and internal floating roof storage tanks:

Tank 168A	Tank 116A	Tank 169A	Tank 154B
Tank 93	Tank 132	Tank 103A	
Tank 94	Tank 159A	Tank 66A	
Tank 113	Tank 164A	Tank 67A	

Seal inspections for these storage tanks are scheduled to begin the week of July 1, 2012.

If you have any questions or need additional information about this notification, please contact me at (610) 364-8120.

Sincerely,

Colin J. Franks
HS&E Manager

Copy To: Mr. Kevin McLemore
Air Quality Program
Pennsylvania Department of Environmental Protection
Southeast Regional Office
2 East Main Street
Norristown, PA 19428
(CERTIFIED MAIL – 7009 2820 0002 5401 0435)

42-045-00070



ConocoPhillips Company
Trainer Refinery
4101 Post Road
Trainer, PA 19061

December 14, 2010

CERTIFIED MAIL 7009 2820 0002 5400 2485

Mr. Andrew Seligman
Environmental Scientist/Enforcement Officer
Air Enforcement Division
3AP12
U.S. Environmental Protection Agency
1650 Arch Street
Philadelphia, Pennsylvania 19103-2029

Subject: Storage Tank Seal Inspection Notification

Dear Mr. Seligman:

ConocoPhillips Company, Trainer Refinery, in accordance with the requirements of 40 CFR § 60.113b(b)(5) and 40 CFR §60.654(h)(2)(ii) notifies the U.S. Environmental Protection Agency with this letter that roof seal inspections and/or seal gap measurements will be completed on the following internal and external floating roof storage tanks during the identified months of 2011:

Tank 66 (Feb)	Tank 116 (Dec)	Tank 161 (Mar)	Tank 171 (Mar)
Tank 67 (Dec)	Tank 132 (Nov)	Tank 162 (Jan)	Tank 178 (Mar)
Tank 68 (Mar)	Tank 134 (Jun)	Tank 163 (Jul)	Tank 184 (Mar)
Tank 93 (Jul)	Tank 151 (May)	Tank 164 (Jun)	
Tank 94 (Jul)	Tank 152 (May)	Tank 165 (Mar)	
Tank 103 (Dec)	Tank 154 (Mar)	Tank 166 (May)	
Tank 113 (Oct)	Tank 156 (Jun)	Tank 168 (Jul)	
Tank 114 (Apr)	Tank 159 (Nov)	Tank 170 (Jun)	

If you have any questions or need any additional information about this notification, please call me at (610) 364-8068.

Sincerely,

Paul W. McDonald
Environmental Engineer

Copy To: Mr. Kevin McLemore
Air Quality Program
Pennsylvania Department of Environmental Protection
2 East Main Street
Norristown, PA 19428
(CERTIFIED MAIL 7009 2820 0002 5400 2492)

RECEIVED
DEC 17 2010
3AP20



ConocoPhillips Company
Trainer Refinery
4101 Post Road
Trainer, PA 19061

December 8, 2010

CERTIFIED MAIL – 7009 2820 0002 5400 2447

Mr. Chris Pilla
Chief, Air Enforcement Branch
U.S. Environmental Protection Agency, Region III
Mail Code 3AP12
1650 Arch Street
Philadelphia, PA 19103-2029

Subject: Tank 154 (TVOP Source ID #139) – Fill Notification

Dear Mr. Pilla:

In accordance with 40 CFR, Subpart Kb, §60.113b(b)(6)(ii), ConocoPhillips Company, Trainer Refinery, submits this letter as a notification to place an aboveground storage tank in service.

Tank 154 (TVOP Source ID #139) is an internal floating roof storage tank that is subject to 40 CFR 60, Subpart Kb regulations. This notification is being made because the storage tank was emptied and degassed for maintenance work; this tank will be refilled no sooner than January 7, 2010.

If you have any questions or comments regarding this notification, please call me at (610) 364-8068.

Sincerely,

Paul W. McDonald
Environmental Engineer

RECEIVED
DEC 13 2010
3AP20

Copy To: Mr. Kevin McLemore
Air Quality
Southeast Regional Office
Pennsylvania Department of Environmental Protection
2 East Main Street
Norristown, PA 19401
(CERTIFIED MAIL – 7009 2820 0002 5400 2430)



ConocoPhillips Company
Trainer Refinery
4101 Post Road
Trainer, PA 19061

December 1, 2010

CERTIFIED MAIL – 7009 2820 0002 5400 2386

Mr. Chris Pilla
Chief, Air Enforcement Branch
U.S. Environmental Protection Agency, Region III
Mail Code 3AP12
1650 Arch Street
Philadelphia, PA 19103-2029

RECEIVED
DEC 03 2010
3AP20

**Subject: Tank 151 (TVOP Source ID #136) - Fill Notification
40 CFR 63, Subpart CC, §63.655**

Dear Mr. Pilla:

In accordance with 40 CFR 63, Subpart CC, §63.655(h)(2)(i), ConocoPhillips Company, Trainer Refinery, submits this letter as a notification to place an aboveground storage tank in service.

Tank 151 (TVOP Source ID #136) is an external floating roof storage tank that is subject to 40 CFR 63, Subpart CC regulations. This notification is being made because the storage tank was emptied and degassed for maintenance work; this tank will be refilled no sooner than December 30, 2010.

If you have any questions or comments regarding this notification, please call me at (610) 364-8068.

Sincerely,



Paul W. McDonald
Environmental Engineer

Copy To: Mr. Kevin McLemore
Air Quality
Southeast Regional Office
Pennsylvania Department of Environmental Protection
2 East Main Street
Norristown, PA 19401
(CERTIFIED MAIL – 7009 2820 0002 5400 2393)



ConocoPhillips Company
Trainer Refinery
4101 Post Road
Trainer, PA 19061

November 23, 2010

CERTIFIED MAIL – 7009 2820 0002 5400 2379

RECEIVED
NOV 30 2010

Mr. Chris Pilla
Chief, Air Enforcement Branch
U.S. Environmental Protection Agency, Region III
Mail Code 3AP12
1650 Arch Street
Philadelphia, PA 19103-2029

**Subject: Tank 164 (TVOP Source ID #147) - Fill Notification
40 CFR 63, Subpart CC, §63.655**

Dear Mr. Pilla:

In accordance with 40 CFR 63, Subpart CC, §63.655(h)(2)(i), ConocoPhillips Company, Trainer Refinery, submits this letter as a notification to place an aboveground storage tank in service.

Tank 164 (TVOP Source ID #146) is an external floating roof storage tank that is subject to 40 CFR 63, Subpart CC regulations. This notification is being made because the storage tank was emptied and degassed for maintenance work; this tank will be refilled no sooner than December 23, 2010.

If you have any questions or comments regarding this notification, please call me at (610) 364-8068.

Sincerely,

Paul W. McDonald
Environmental Engineer

Copy To: Mr. Kevin McLemore
Air Quality
Southeast Regional Office
Pennsylvania Department of Environmental Protection
2 East Main Street
Norristown, PA 19401